Fire risk assessment checklist – Small premises with paying guests

Responsible person (e.g. employer) or person having control of the premises:	Amy & Ted Langdon		
Address of premises:	Glenhope, Bryher, Isles of Scilly, TR23 0PR		
Number of floors:	Number of rooms: 5		
Construction:	Granite, slate roof, concrete block extension		
Date of fire risk assessment:	12/03/2024		
Date of previous fire risk assessment:	07/09/2023		
Suggested date for review:	30/11/2024		

Fire hazards and controls

Are fixed electrical installations in	spected and tested every	/ 5 v	vears?
	- p	_	,

Yes **√**/ No□ Carried out by the Duchy of Cornwall as landlord.

Are electrical appliances periodically inspected and tested?

N/A ☐ Yes ✓ No☐ Inspected by proprietors at every changeover. PAT testing carried out by Graham Eggins 13/01/2024.

Is the use of trailing leads and adaptors avoided where possible?
Yes \checkmark No \square An extension lead/surge protector is used for the TV, Sky etc.
Are gas appliances inspected and tested every 12 months?
N/A √ Yes □ No□
Is smoking permitted on the premises?
Yes □ No ✓
Are suitable arrangements in place for those who wish to smoke?
N/A \square Yes \checkmark No \square Guests may smoke in the garden if they wish.
Are the premises adequately secured to prevent unauthorised access?
Yes ✓ No□
Are combustible materials, waste and refuse bins stored safely clear of the premises or in purpose-built compounds/rooms?
Yes ✓ No□
Are fixed heating systems subject to periodic maintenance?
N/A □ Yes ✔ No□
Are portable heaters subject to periodic inspection and used safely?
N/A ✓ Yes □ No□ Portable heaters are not provided.
Are there adequate fire precautions in the use of open fires and log burners? e.g. regular chimney sweeping
N/A ✓ Yes □ No□ All heating is electric.
Are adequate measures taken to prevent fires from cooking equipment? e.g. prohibiting deep fat fryers
N/A □ Yes ✔ No□
Are filters and ductwork subject to regular cleaning?
N/A □ Yes ✓ No□

Is the standard of housekeeping adequate to avoid the accumulation of combustible materials and waste e.g. from tumble dryers?
Yes ✔ No□ The tumble dryer filter is cleaned and all bins are emptied at every changeover.
Are combustible materials kept separate from ignition and heat sources?
Yes √ No□
Is it ensured that all contractors who undertake work on the premises are competent and qualified?
Yes √ No□
Are suitable measures in place to address the fire hazards associated with the use and storage of dangerous substances?
N/A √ Yes □ No□
Are there any other significant fire hazards in the premises?
Yes √ No□
If the answer to the above question is yes, please list each hazard and any control measure to reduce the

risk of fire, in the box below. If the answer to any question is no, include suitable action within the Action

LOW RISK:

Plan.

Electric heaters in all rooms (we have not provided a hook on the back of the twin bedroom door as this may lead to clothes / towels being too near the heater).

Kitchen – electric cooker, hob and microwave. A fire blanket & fire extinguisher are provided in the kitchen.

There is no door between the kitchen and the dining/living room, just a narrow passage way. A fire blanket is provided on the upstairs landing to protect guests having to come downstairs and past the entry to the kitchen in order to escape via the front entrance door.

Fire protection measures

Are all escape routes kept clear of obstructions to enable people to escape safely?
Yes √ No□
Are all fire exits easily and immediately openable?
Yes \checkmark No \square Thumb locks have been installed to front and rear entrance doors.
Are distances to final exits considered reasonable?
Yes ✓ No□
Do the walls and structures protecting the stairway and escape routes provide an adequate level of fire resistance?
N/A □ Yes ✓ No□
Is the fire resistance of doors to stairways and escape routes considered adequate?
N/A \square Yes \checkmark No \square FD30 doors fitted to bedrooms January 2024. An additional fire blanket provided on upstairs landing to protect guests having to exit down the stairs.
Where necessary, are doors fitted with suitable self-closing devices that close the doors effectively?
N/A ✓ Yes □ No□
Are there adequate levels of artificial lighting provided in the escape routes?
Yes ✓ No□ NiteSafe Sensor 11 Safety lights in both bedrooms and positioned below open tread stairs to light escape route.
Where necessary, has a reasonable standard of emergency escape lighting been provided?
N/A □ Yes ✓ No□
Where necessary, is a reasonable standard of fire exit and fire safety signs provided?
N/A □ Yes ✓ No□
N/A ☐ Yes ✓ No☐ Are smoke and/or heat alarms/detectors provided and is the extent and coverage considered adequate? Consider also CO alarms.

Is there a reasonable provision of firefighting equipment (fire extinguishers, fire blankets)?
Yes √ No□
Record brief details of the above measures in the box below. If the answer to any question is no, include suitable action within the Action Plan.
Mains linked smoke / heat detectors in each room. Multi-purpose fire
extinguisher and fire blanket in kitchen. Additional fire blanket on upstairs
landing to protect guests having to go past kitchen entry on coming down the
stairs. Two escape routes via front and rear entrance doors. NiteSafe Sensor 11
Safety lights in both bedrooms and positioned below the staircase (open treads)
to light escape route.
Awaiting further Government guidance with regard to fire safety
recommendations in open plan premises.
Management of fire safety
Are procedures in the event of fire appropriate and documented?
Yes √ No□
Is the information on fire safety and the action to take in the event of a fire given to guests?
Yes √ No□
Are any staff members given regular instruction and training on the action to take in the event of a fire?
N/A \checkmark Yes \square No \square Self contained self catering holiday accommodation.
Are frequent checks carried out to ensure exit routes are kept clear and fire exits remain easily openable?
Yes ✓ No□
Are periodic checks carried out on fire doors to ensure they remain in good condition and close effectively?
N/A □ Yes ✓ No□

Are domestic smoke and heat alarms tested at least monthly? Include CO alarms in testing.
Yes √ No□
Where fitted, are weekly testing and six-monthly servicing routines in place for the fire detection and alarm system?
N/A √ Yes □ No□
In self-catering premises, are all smoke/heat alarms (or fire detection and alarm systems, where fitted) tested at every changeover?
N/A □ Yes ✓ No□
Where fitted, are monthly and annual testing routines in place for the emergency escape lighting?
N/A □ Yes √ No□
Where provided, are fire extinguishers subject to annual maintenance?
N/A □ Yes √ No□ Pressure is visually checked annually.
Are records of testing and maintenance maintained?
Yes √ No□
Record brief details of the above measures in the box below. If the answer to any question is no, include suitable action within the Action Plan.

Fire safety information for guests is provided in the guest information. Fire Action Notice is clearly displayed. Smoke / heat alarms and NiteSafe Safety lights are checked at every changeover.

Action plan

If any of the above boxes are ticked with a 'No', the deficiencies should be described below, along with proposed action for rectification.

Item	Deficiency	Proposed action	Timescale	Person responsible